

Water Testing Results to Date
Updated: 1/18/2019

As previously communicated, water samples have been collected from all occupied buildings on the NJIT campus. Additional samples are being collected periodically; following the repair or replacement of plumbing fixtures, the installation of point of use filtration devices, or randomly at various campus locations. Please note that results are reported in PPB (parts per billion) which is equivalent to microgram per liter (ug/L). ND stands for “None Detected” which means that the results are below the laboratory’s limit of analytical detection.

Drinking Water Sampling Field Sheet
Sampled on: January 10, 2019
Received Results on: January 17, 2019

Building	Location	Notes	Sample Type	Results PPB
Laurel Hall Ext.	Security/Photo ID Kitchen		G	ND
Tiernan Hall	3 rd Floor Drinking Fountain	Drinking Fountain	G	ND
Tiernan Hall	3 rd Floor Drinking Fountain	Bottle Filler	G	ND
GITC	Room 4425 Kitchen Sink		G	ND

Drinking Water Sampling Field Sheet
Sampled on: November 7, 2018
Received Results on: November 20, 2018

Building	Location	Notes	Sample Type	Results PPB
Public Safety	1 st Floor Pantry		G	ND
Oak	1 st Floor Pantry	To be repaired and retested	G	24
WEC	Hydration Station	1A10.03	G	ND
GITC	3 rd Floor Pantry	Room 3501	G	ND
Campus Center	Main Kitchen- Food Prep Sink	Across from Steam Table	G	ND
Fenster Hall	5 th Floor Pantry	Room 588	G	ND

Drinking Water Sampling Field Sheet
Sampled on: May 10, 2018
Received Results on: May 17, 2018

Building	Location	Notes	Sample Type	Results PPB
Tiernan	1 st Floor Drinking Fountain	Across from Rm. 199	G	ND
Tiernan	2 nd Floor Drinking Fountain	Across from Rm. 299	G	6.0
Oak	1 st Floor Drinking Fountain	Lobby Area	G	ND
Oak	1 st Floor Kitchen	Resample after additional pipe replacement	F	ND

Drinking Water Sampling Field Sheet
Sampled on: March 28, 2018
Received Results on: April 5, 2018

Building	Location	Notes	Sample Type	Results PPB
Oak	1 st Floor Kitchen	Resample after additional shut-off valve replacement	F	139

Drinking Water Sampling Field Sheet
Sampled on: February 13, 2018
Received Results on: February 20, 2018

Building	Location	Notes	Sample Type	Results PPB
Oak	1 st Floor Kitchen	Resample after valve, faucet and tube replacement	F	227
EDC	1 st Floor Kitchen	Resample	F	3.5
Microelectronics	2 nd Floor Drinking Fountain		G	ND
Mechanical Eng.	2 nd Floor Drinking Fountain	Upper Fixture	G	7.2
Mechanical Eng.	2 nd Floor Drinking Fountain	Lower Fixture	G	1.9
Wellness Center	Drinking Fountain	1A10.03	G	ND
Wellness Center	Drinking Fountain	2A10.02	G	ND
Wellness Center	Kitchen Sink-Hospitality		G	ND
Wellness Center	Kitchen Sink-Break Rm.		G	ND
Wellness Center	Kitchen Sink-Athlete Lounge		G	ND

Drinking Water Sampling Field Sheet**Sampled on: January 4, 2018****Received Results on: January 16, 2018**

Building	Location	Notes	Sample Type	Results PPB
Weston	Drinking Fountain 3 rd Floor		G	ND
Weston	Kitchen 351		G	ND
Weston	Drinking Fountain 3 rd Floor	Bottle Filler	G	ND
Weston	Kitchen 350A		G	ND
Weston	Drinking Fountain 4 th Floor		G	ND
Weston	Drinking Fountain 5 th Floor		G	ND
Weston	Drinking Fountain 6 th Floor		G	ND
Weston	Drinking Fountain 7 th Floor		G	ND
Weston	Drinking Fountain 2 nd Floor		G	ND
Weston	Drinking Fountain 1 st Floor		G	ND
GITC	Drinking Fountain 1 st Floor	Left	G	ND
GITC	Drinking Fountain 1 st Floor	Right	G	ND
GITC	Kitchen 2111		G	ND
GITC	Drinking Fountain 3 rd Floor		G	ND
GITC	Drinking Fountain 4 th Floor	Right	G	ND
GITC	Drinking Fountain 4 th Floor	Left	G	ND
GITC	Drinking Fountain 5 th Floor	Left	G	ND
GITC	Drinking Fountain 5 th Floor	Right	G	ND
GITC	Kitchen 0300		G	8.3
GITC	Drinking Fountain 2 nd Floor	Near Robotics Lab 2ITC Sign	G	ND
Mechanical	Drinking Fountain 3 rd Floor	Lower	G	1.1
Mechanical	Drinking Fountain 3 rd Floor	Upper	G	ND
Mechanical	Drinking Fountain 2 nd Floor	Upper - Fountain to be repaired and retested	G	49.0
Mechanical	Drinking Fountain 2 nd Floor	Lower - Fountain to be repaired and retested	G	25.7
Central King	Drinking Fountain 1 st Floor	Upper	G	ND
Central King	Drinking Fountain 1 st Floor	Lower	G	ND
Central King	Drinking Fountain 1 st Floor	Bottle Filler	G	ND
Central King	Drinking Fountain 2 nd Floor	Upper	G	ND
Central King	Drinking Fountain 2 nd Floor	Lower	G	ND
Central King	Drinking Fountain 3 rd Floor	Near Room 317	G	ND

Drinking Water Sampling Field Sheet
Sampled on: December 14, 2017
Received Results on: December 22, 2017

Building	Location	Notes	Sample Type	Results PPB
Campus Center	Grains Hand Sink		G	3.6
Campus Center	Grains Pot Sink		G	1.8
Campus Center	Bonsai Kitchen Sink		G	ND
Campus Center	Salads Kitchen Sink		G	1.6
Campus Center	Taco Bell Kitchen Sink		G	1.0
Campus Center	Starbucks Kitchen Hand Sink		G	9.9
Campus Center	Starbucks Pot Sink		G	ND
Campus Center	Drinking Fountain 176		G	ND
Campus Center	Fortes Pizza Kitchen		G	1.4
Campus Center	Kitchen Sink	Near Emergency Exit	G	ND
Campus Center	Second Floor Drinking Fountain		G	ND
Campus Center	Fourth Floor Drinking Fountain	Upper	G	ND
Campus Center	Fourth Floor Drinking Fountain	Lower	G	ND
Campus Center	Fourth Floor Drinking Fountain	Upper - WBR	G	ND
Campus Center	Fourth Floor Drinking Fountain		G	ND
Fenster	University Admissions Kitchen		G	ND
Central Avenue Bldg.	Drinking Fountain Entrance		G	ND
Central Avenue Bldg.	Drinking Fountain Entrance	Bottle Filler	G	ND
Central Avenue Bldg.	Second Floor Drinking Fountain		G	ND
Central Avenue Bldg.	Second Floor Drinking Fountain	Bottle Filler	G	ND
Central Avenue Bldg.	Basement Drinking Fountain	Lower	G	ND
Central Avenue Bldg.	Basement Drinking Fountain	Upper	G	ND
Central Avenue Bldg.	Second Floor Kitchen 2033		G	ND
Central Avenue Bldg.	Second Floor Kitchen	School of Management	G	ND
Central Avenue Bldg.	Second Floor Kitchen Drinking Fountain	School of Management	G	ND

Drinking Water Sampling Field Sheet
Sampled on: December 11, 2017
Received Results on: December 18, 2017

Building	Location	Notes	Sample Type	Results PPB
Cullimore	First Floor Drinking Fountain		G	ND
Cullimore	Kitchen 201		G	2.1
Cullimore	Kitchen 348		G	1.8
Cullimore	Kitchen 150		G	1.7
Cullimore	Basement Drinking Fountain		G	1.4
Eberhardt	Basement Drinking Fountain		G	ND
Eberhardt	Basement Drinking Fountain		G	ND
Eberhardt	Basement Drinking Fountain		G	2.0
Eberhardt	First Floor Drinking Fountain		G	ND
Eberhardt	First Floor Drinking Fountain		G	ND
Eberhardt	First Floor Drinking Fountain		G	ND
Fenster	Drinking Fountain 128		G	ND
Fenster	Drinking Fountain 129		G	ND
Fenster	Drinking Fountain 229	Lower	G	ND
Fenster	Drinking Fountain 229		G	ND
Fenster	Drinking Fountain 329		G	ND
Fenster	Drinking Fountain 328		G	ND
Fenster	Drinking Fountain 429		G	ND
Fenster	Drinking Fountain 428		G	ND
Fenster	Drinking Fountain 528		G	ND
Fenster	Drinking Fountain 529		G	ND
Fenster	Drinking Fountain 629	Lower	G	ND
Fenster	Drinking Fountain 629		G	ND
Campus Center	Highlander Pub	Kitchen	G	ND

Drinking Water Sampling Field Sheet
Sampled on: December 8, 2017
Received Results on: December 18, 2017

Building	Location	Notes	Sample Type	Results PPB
ECE	First Floor Drinking Fountain		G	ND
ECE	Kitchen 201		G	2.9
ECE	Kitchen 348		G	3.8
Tiernan	Kitchen 150		G	ND
Kupfrian	Basement Drinking Fountain		G	1.7
Kupfrian	Basement Drinking Fountain		G	ND
Kupfrian	Basement Drinking Fountain		G	ND
Kupfrian	Basement Drinking Fountain		G	ND
Kupfrian	First Floor Drinking Fountain		G	ND
Kupfrian	First Floor Drinking Fountain		G	ND
Kupfrian	First Floor Drinking Fountain		G	1.6
Colton	Kitchen Room 216		G	ND
Colton	Drinking Fountain Room 263		G	ND
Colton	Drinking Fountain Room 324		G	ND
Colton	Drinking Fountain Room 424		G	ND
Campbell Hall	Kitchen 402		G	ND
Campbell Hall	Second Floor Drinking Fountain		G	ND
Campbell Hall	Kitchen 5 th Floor		G	ND
Campbell Hall	Fifth Floor Drinking Fountain		G	ND
Campbell Hall	Kitchen Pantry 302		G	ND
Campbell Hall	Drinking Fountain 302		G	ND

Drinking Water Sampling Field Sheet
Sampled on: December 5, 2017
Received Results on: December 15, 2017

Building	Location	Notes	Sample Type	Results PPB
Public Safety	First Floor Kitchen		G	ND
Oak	First Floor Kitchen	Faucet Replaced, Valves to be replaced and resampled	G	51.9
Laurel	First Floor Kitchen		G	ND
Greek 7	First Floor Kitchen		G	ND
Greek 9	First Floor Kitchen		G	ND
Greek 15	First Floor Kitchen		G	ND
Greek 17	First Floor Kitchen		G	ND
Greek 23	First Floor Kitchen		G	ND
Student Mall	First Floor Kitchen		G	ND
Laurel	First Floor Pantry	Security Systems – Laurel Annex	G	ND
Cypress	Third Floor Kitchen		G	1.9
CHEN	First Floor Kitchen		G	1.2
EDC	Daycare	Large Washing Sink - Faucet and valves to be replaced and resampled	G	34.8
EDC	Daycare	Washing Sink	G	1.9
Tiernan	436-A		G	ND

Drinking Water Sampling Field Sheet
Sampled on: December 5, 2017
Received Results on: December 15, 2017

Building	Location	Notes	Sample Type	Results PPB
Micro-electronics	2 nd Floor Drinking Fountain	Hallway outside room 299B (right hand fixture) To be repaired and resampled	G	14.6
Micro-electronics	2 nd Floor Drinking Fountain	Hallway outside room 299B (left hand fixture)	G	ND
Micro-electronics	2 nd Floor Drinking Fountain	Hallway outside room 299C	G	1
Micro-electronics	4 th Floor Drinking Fountain	Hallway outside room 499B	G	ND
Tiernan	1 st Floor Drinking Fountain	Hallway outside room 199 D	G	3
Tiernan	1 st Floor Drinking Fountain	Hallway outside room 199 D	G	4
Tiernan	1 st Floor Drinking Fountain	Hallway outside room 199 B	G	ND
Tiernan	2 nd Floor Drinking Fountain	Hallway outside room 299 C	G	ND
Tiernan	3 rd Floor Drinking Fountain	Hallway outside room 399 C	G	ND
Tiernan	3 rd Floor Drinking Fountain	Hallway outside room 399 D	G	ND
Tiernan	4 th Floor Drinking Fountain	Hallway outside room 499 D	G	4.7
Micro-electronics	3 rd Floor Drinking Fountain	Hallway outside room 399 B	G	5.7
Micro-electronics	3 rd Floor Drinking Fountain	Hallway outside room 399 B	G	2.8
Micro-electronics	2 nd Floor Drinking Fountain	Hallway outside room 299 B	G	ND
Tiernan	3 rd Floor Drinking Fountain	Hallway outside room 399 D	G	ND

Drinking Water Sampling Field Sheet
Sampled on: December 16, 2016
Received Results on: December 23, 2016

Building	Location	Notes	Sample Type	Results PPB
Oak	Mechanical Room –Water In (before valves and fittings)	Retest Flush 30 Sec.	F	0.7
Oak	Mechanical Room –Water In (before valves and fittings)	Retest Flush 30 Sec.	F	4.1
Oak	Oak Kitchen Sink, Room 103	Retest Flush 30 Sec.	F	3.0
Oak	Oak Kitchen Sink, Room 803	Initial Sample – Previously Untested - Grab	G	5.5
Oak	Oak Kitchen Sink, Room 706	Initial Sample – Previously Untested - Grab	G	3.8
Oak	Oak Kitchen Sink, Room 609	Initial Sample – Previously Untested - Grab	G	9.0
Oak	Oak Kitchen Sink, Room 502	Initial Sample – Previously Untested - Grab	G	1.5
Oak	Oak Kitchen Sink, Room 401	Initial Sample – Previously Untested - Grab	G	1.1
Oak	Oak Kitchen Sink, Room 303	Initial Sample – Previously Untested - Grab	G	13.2
Oak	Oak Kitchen Sink, Room 205	Initial Sample – Previously Untested - Grab	G	1.1
Tiernan	Drinking Fountain -Basement	Newly Installed – to be repaired and re-sampled	G	18.2
Tiernan	Drinking Fountain -2 nd Floor	Newly Installed	G	1.5
Tiernan	Drinking Fountain -3 rd Floor	Newly Installed	G	ND
Tiernan	Drinking Fountain -4 th Floor	Newly Installed	G	8

Drinking Water Sampling Field Sheet
Sampled on: December, 1 2016
Received Results on December 8, 2016

Building	Location	Notes	Sample Type	Results PPB
Oak	Mechanical Room –Water In (before valves and fittings)		G	33.8
Oak	Mechanical Room –Water In (before valves and fittings)		G	47.1
Oak	Oak kitchen sink 804		G	2.0
Oak	Oak kitchen sink 608		G	10.8
Oak	Oak kitchen sink 506		G	3.8
Oak	Oak kitchen sink 202		G	11.0
Oak	Oak kitchen sink 206		G	6.9
Oak	Oak kitchen sink 103	To be repaired and re-tested	G	18.4
Oak	Mechanical Room –Water Out (after valves and fittings)	Valves and fittings in mechanical room replaced	G	ND

Drinking Water Sampling Field Sheet
Sampled on: October 27, 2016
Received Results on: November 3, 2016

Building	Location	Notes	Sample Type	Results PPB
Tiernan	4 th floor loading dock side	Fountain components replaced	G	2.1
Tiernan	2 nd floor loading dock side	Fountain components replaced	G	9.9

Drinking Water Sampling Field Sheet
Sampled on: September 26, 2016
Received Results on: October 13, 2016

Building	Location	Notes	Sample Type	Results PPB
Oak	Mechanical Room – Water In (before valves and fittings)	N/A	G	7.9
Oak	Mechanical Room – Water Out (after valves and fittings)	Mechanical room valves and fittings to be replaced and retested	G	22.6

Drinking Water Sampling Field Sheet
Sampled on: September, 7 2016
Received Results on: September 14, 2016

Building	Location	Notes	Sample Type	Results PPB
Cullimore	Water fountain 5th floor	Fountain Replaced	G	1
Tiernan	Water fountain 4 th floor	To be repaired and re-tested	G	14
Tiernan	Water fountain 3 rd floor	N/A	G	1
Tiernan	Water fountain 2 nd floor	To be repaired and re-tested	G	19
Tiernan	Water fountain 1 st floor	N/A	G	5
Tiernan	Water fountain basement	N/A	G	5
Oak	Oak Kitchen sink 809	Faucet, valves, tubes replaced	G	4
Oak	Oak Kitchen sink 808	Faucet, valves, tubes replaced	G	4
Oak	Oak Kitchen sink 804	Faucet, valves, tubes replaced	G	19
Oak	Oak Kitchen sink 702	Faucet, valves, tubes replaced	G	13
Oak	Oak Kitchen sink 709	Faucet, valves, tubes replaced	G	10
Oak	Oak Kitchen sink 608	Faucet, valves, tubes replaced	G	15
Oak	Oak Kitchen sink 506	Faucet, valves, tubes replaced	G	15
Oak	Oak Kitchen sink 202	Faucet, valves, tubes replaced	G	189
Oak	Oak Kitchen sink 206	Faucet, valves, tubes replaced	G	50
Oak	Oak Kitchen sink 103	Faucet, valves, tubes replaced	G	48
Additional samples collected in Oak Hall mechanical room at water entry point and after valves and fittings				

Drinking Water Sampling Field Sheet
Sampled on: August 25, 2016
Received Results on: September 6, 2016

Building	Location	Notes	Sample Type	Results PPB
Cypress	Room 802 lavatory sink	N/A	G	12
Cypress	Room 703 lavatory sink	N/A	G	14
Cypress	6 th floor study lounge near 604	N/A	G	ND
Cypress	Room 517 lavatory sink	N/A	G	3
Cypress	Room 418 lavatory sink	N/A	G	3
Cypress	3 rd floor study lounge near 314	N/A	G	2
Cypress	Room 213 lavatory sink	N/A	G	7
Cypress	First floor restroom lavatory sink	N/A	G	2

Drinking Water Sampling Field Sheet
Sampled on: August 18, 2016
Received Results on: August 25, 2016

Building	Location	Notes	Sample Type	Results PPB
Oak	Room 809 Kitchen Sink	To be repaired and re-tested	G	66
Oak	Room 804 Kitchen Sink	To be repaired and re-tested	G	19
Oak	Room 702 Kitchen Sink	To be repaired and re-tested	G	27
Oak	Room 709 Kitchen Sink	To be repaired and re-tested	G	575
Oak	Room 608 Kitchen Sink	To be repaired and re-tested	G	25
Oak	Room 601 Kitchen Sink	N/A	G	11
Oak	Room 504 Kitchen Sink	N/A	G	11
Oak	Room 506 Kitchen Sink	To be repaired and re-tested	G	26
Oak	Room 404 Kitchen Sink	N/A	G	12
Oak	Room 408 Kitchen Sink	N/A	G	11
Oak	Room 309 Kitchen Sink	N/A	G	8
Oak	Room 301 Kitchen Sink	N/A	G	6
Oak	Room 202 Kitchen Sink	To be repaired and re-tested	G	578
Oak	Room 206 Kitchen Sink	To be repaired and re-tested	G	24
Oak	Room 105 Kitchen Sink	N/A	G	10
Oak	Room 103 Kitchen Sink	To be repaired and re-tested	G	46

Drinking Water Sampling Field Sheet
Sampled on: August 3, 2016
Received Results on: August 11, 2016

Building	Location	Notes	Sample Type	Results PPB
Laurel	Room 731 Lavatory Sink	NA	G	ND
Laurel	Room 726 Lavatory Sink	NA	G	ND
Laurel	Room 630 Lavatory Sink	NA	G	ND
Laurel	Room 621 Lavatory Sink	NA	G	ND
Laurel	Room 527 Lavatory Sink	NA	G	ND
Laurel	Room 524 Lavatory Sink	NA	G	ND
Laurel	Room 519 Lavatory Sink	NA	G	ND
Laurel	Room 509 Lavatory Sink	NA	G	ND
Laurel	Room 404 Lavatory Sink	NA	G	ND
Laurel	Room 410 Lavatory Sink	NA	G	ND
Laurel	Room 423 Lavatory Sink	NA	G	ND
Laurel	Room 426 Lavatory Sink	NA	G	ND
Laurel	Room 326 Lavatory Sink	NA	G	7
Laurel	Room 322 Lavatory Sink	NA	G	1
Laurel	Room 320 Lavatory Sink	NA	G	ND
Laurel	Room 316 Lavatory Sink	NA	G	2
Laurel	Room 218 Lavatory Sink	NA	G	ND
Laurel	Room 212 Lavatory Sink	NA	G	ND
Laurel	Room 228 Lavatory Sink	NA	G	ND
Laurel	Room 126 Lavatory Sink	NA	G	1
Laurel	Room 025 Lavatory Sink	NA	G	2
Laurel	Laundry Room Sink	NA	G	ND
Laurel	Room 108 Lavatory Sink	NA	G	ND

Drinking Water Sampling Field Sheet
Sampled on: July 28, 2016
Received Results on: August 4, 2016

Building	Location	Notes	Sample Type	Results PPB
Oak Hall	Room 809 - In-Suite Lavatory Sink	To be repaired and re-tested	G	13
Oak Hall	Room 808 - In-Suite Lavatory Sink	To be repaired and re-tested	G	24
Oak Hall	Room 707 - In-Suite Lavatory Sink	To be repaired and re-tested	G	44
Oak Hall	Room 706 - In-Suite Lavatory Sink	To be repaired and re-tested	G	46
Oak Hall	Room 600 - In-Suite Lavatory Sink	To be repaired and re-tested	G	19
Oak Hall	Room 601 - In-Suite Lavatory Sink	To be repaired and re-tested	G	16
Oak Hall	Room 503 - In-Suite Lavatory Sink	To be repaired and re-tested	G	45
Oak Hall	Room 504 - In-Suite Lavatory Sink		G	9
Oak Hall	Room 407 - In-Suite Lavatory Sink	To be repaired and re-tested	G	15
Oak Hall	Room 409 - In-Suite Lavatory Sink	To be repaired and re-tested	G	15
Oak Hall	Room 308 - In-Suite Lavatory Sink	To be repaired and re-tested	G	20
Oak Hall	Room 309 - In-Suite Lavatory Sink	To be repaired and re-tested	G	30
Oak Hall	Room 205 - In-Suite Lavatory Sink		G	8
Oak Hall	Room 200 - In-Suite Lavatory Sink	To be repaired and re-tested	G	40
Oak Hall	Room 102 - In-Suite Lavatory Sink	To be repaired and re-tested	G	260
Oak Hall	1 st Floor Rest Room Lavatory Sink	To be repaired and re-tested	G	10

Drinking Water Sampling Field Sheet
Sampled on: July 27, 2016
Received Results on: August 4, 2016

Building	Location	Notes	Sample Type	Results PPB
Cypress Hall	Room 818 - In-Suite Lavatory Sink	N/A	G	ND
Cypress Hall	Room 716 - In-Suite Lavatory Sink	N/A	G	1
Cypress Hall	Room 614 - In-Suite Lavatory Sink	N/A	G	ND
Cypress Hall	Room 515 - In-Suite Lavatory Sink	N/A	G	ND
Cypress Hall	Room 413 - In-Suite Lavatory Sink	N/A	G	5
Cypress Hall	Room 312 - In-Suite Lavatory Sink	N/A	G	4
Cypress Hall	Room 211 - In-Suite Lavatory Sink	N/A	G	1
Cypress Hall	Room 112 - Rest Room Lavatory Sink	N/A	G	ND
Cypress Hall	Men's Room - Rest Room Lavatory Sink	N/A	G	ND

Drinking Water Sampling Field Sheet
Sampled on: July 27, 2016
Received Results on: August 4, 2016

Building	Location	Notes	Sample Type	Results PPB
Cypress Hall	Room 801 - In-Suite Lavatory Sink	N/A	G	ND
Cypress Hall	Room 703 - In-Suite Lavatory Sink	N/A	G	2
Cypress Hall	Room 624 - Rest Room Lavatory Sink	N/A	G	ND
Cypress Hall	Room 505 - In-Suite Lavatory Sink	N/A	G	1
Cypress Hall	Room 407 - In-Suite Lavatory Sink	N/A	G	3
Cypress Hall	Room 306 - In-Suite Lavatory Sink	N/A	G	14
Cypress Hall	Room 209 - In-Suite Lavatory Sink	N/A	G	1

Drinking Water Sampling Field Sheet
Sampled on: July 7, 2016
Received Results on: July 12, 2016

Building	Location	Notes	Sample Type	Results PPB
Colton Hall	2 nd Floor Drinking Fountain	N/A	G	ND
Colton Hall	4 th Floor Drinking Fountain	N/A	G	ND
Cullimore	5 th Floor Drinking Fountain	N/A	G	37

Drinking Water Sampling Field Sheet
Sampled on: June 30, 2016
Received Results on: July 6, 2016

Building	Location	Action	Sample Type	Results PPB
Weston Hall	2 nd Floor Drinking Fountain	N/A	G	2
Weston Hall	4 th Floor Drinking Fountain	N/A	G	ND
Weston Hall	5 th Floor Drinking Fountain	N/A	G	ND
Weston Hall	6 th Floor Drinking Fountain	N/A	G	ND
Colton Hall	3 rd Floor Drinking Fountain	N/A	G	1
Kupfrian Hall	1 st Floor Lobby Drinking Fountain (a)	N/A	G	ND
Kupfrian Hall	1 st Floor Lobby Drinking Fountain (b)	N/A	G	2
Kupfrian Hall	1 st Floor Lobby Drinking Fountain (c)	N/A	G	ND
Kupfrian Hall	Basement Drinking Fountain (a)	N/A	G	ND
Kupfrian Hall	Basement Drinking Fountain (b)	N/A	G	2
Kupfrian Hall	Basement Drinking Fountain (d)	N/A	G	ND
Kupfrian Hall	Basement Drinking Fountain (f)	N/A	G	1

Drinking Water Sampling Field Sheet
Sampled on: June 22, 2016
Received Results on: June 28, 2016

Building	Location	Action	Sample Type	Results PPB
Fleisher Athletic Center	Sink Laundry/Registration Area	N/A	G	1
Fleisher Athletic Center	Sink Athletic Training Room	N/A	G	ND
Cullimore Hall	5 th Floor Drinking Fountain	Replaced Internal Components on 6/21/16	G	28
Cullimore Hall	5 th Floor Drinking Fountain	(Fountain to be re-serviced and then re-sampled)		

Drinking Water Sampling Field Sheet
Sampled on: June 17, 2016
Received Results on: June 24, 2016

Building	Location	Action	Sample Type	Results PPB
Weston	7 th Floor Drinking Fountain	N/A	G	6
Weston	1 st Floor Drinking Fountain	N/A	G	1

Drinking Water Sampling Field Sheet
Sampled on: June 9, 2016
Received Results on: June 17, 2016

Building	Location	Action	Sample Type	Results PPB
Weston	3 rd Floor New Hydration Station	Installed on 6/6/2016	G	ND
Cullimore	2 nd Floor Drinking Fountain	Installed new internal components on 6/6/2016	G	3
Cullimore	4 th Floor Drinking Fountain	Installed new internal components on 6/6/2016	G	1
Cullimore	5 th Floor Drinking Fountain	Installed new internal components on 6/6/2016 – Fixture to be re-serviced	G	39
Eberhardt	3 rd Floor Drinking Fountain	Turned on and Flushed on 6/7/2016	G	2
Eberhardt	2 nd Floor Drinking Fountain	Turned on and Flushed on: 6/7/2016	G	ND
Eberhardt	1 st Floor Drinking Fountain	Turned on and Flushed on: 6/7/2016	G	3

Drinking Water Sampling Field Sheet
Sampled on: Wednesday May 25, 2016
Received Results on: June 3, 2016

Building	Location	Action	Sample Type	Results PPB
GITC	1 st Floor Hallway Drinking Fountain - Left	N/A	Grab	ND
GITC	1 st Floor Hallway Drinking Fountain - Right	N/A	Grab	ND
GITC	2 nd Floor Hallway Drinking Fountain - Left	N/A	Grab	ND
GITC	2 nd Floor Hallway Drinking Fountain - Right	N/A	Grab	ND
GITC	3 rd Floor Hallway Drinking Fountain	N/A	Grab	ND
GITC	4 th Floor Pantry Sink - Room 4417	N/A	Grab	ND

Drinking Water Sampling Field Sheet
Sampled on: Thursday May 26, 2016
Received Results on: June 3, 2016

Building	Location	Action	Sample Type	Results PPB
Tiernan Hall	1 st Floor Hallway Hydration Station	Replaced Drinking Fountain	Grab	4
Cullimore	3 rd Floor Pantry Sink - Room 330	N/A	Grab	ND
GITC	Basement Hallway Drinking Fountain - Left	N/A	Grab	ND
GITC	Basement Hallway Drinking Fountain - Right	N/A	Grab	ND
Student Mall	Hallway Drinking Fountain Adjacent to Room 22	N/A	Grab	ND
Student Mall	Pantry Sink - Room 16	N/A	Grab	ND
Student Mall	Hallway Drinking Fountain Adjacent to Room 35	N/A	Grab	ND

Drinking Water Sampling Locations and Results
Sampled on: Thursday May 19, 2016
Received Results on: May 24, 2016

Building	Location	Action	Sample Type	Results PPB
Fleisher Athletic	Drinking Fountain Across from Racquetball Courts	N/A	Grab	ND
Eberhardt Hall	1 st Floor Pantry Sink (room 108)	Replaced Valves	Grab	ND
Cullimore Hall	1 st Floor Drinking Fountain Outside Elevators	Replaced Fountain Components	Grab	11
Cullimore Hall	3 rd Floor Drinking Fountain Outside Elevators	Replaced Fountain Components	Grab	3
Cullimore Hall	6 th Floor Drinking Fountain Outside Elevators	Replaced Fountain Components	Grab	3
5 Greek Way	Kitchen Sink w/o Filter	New Backflow Prevention Device and Shut Off Valve	Flush 30	ND
Weston Hall	3 rd Floor Drinking Fountain	Replaced Fountain Components	Grab	3
Campbell Hall	3 rd Floor Pantry Sink (room # 303)	N/A	Grab	ND
Campbell Hall	5 th Floor Pantry Sink (room 507)	Replaced Faucet and Valves	Grab	10
Campbell Hall	3 rd Floor Drinking Fountain	N/A	Grab	ND
Campbell Hall	4 th Floor Drinking Fountain	N/A	Grab	ND
Campbell Hall	5 th Floor Drinking Fountain	N/A	Grab	ND

Drinking Water Sampling Locations and Results
Date Sampled: Wednesday May 12, 2016
Results Received: May 19, 2016

Building	Location	Action	Sample Type	Results PPB
13 Greek Way	Pot Sink without Filter	New Backflow Prevention Device and Shut Off Valve	Flush 30	1
11 Greek Way	Pot Sink without Filter	New Backflow Prevention Device and Shut Off Valve	Flush 30	ND
7 Greek Way	Pot Sink without Filter	New Backflow Prevention Device and Shut Off Valve	Flush 30	ND

Drinking Water Sampling Locations and Results
Date Sampled: Wednesday May 11, 2016
Results Received: May 19, 2016

Building	Location	Action	Sample Type	Results PPB
23 Greek Way	Pot Sink without Filter	New Backflow Prevention Device and Shut Off Valve	Flush 30	ND
19 Greek Way	Pot Sink without Filter	New Backflow Prevention Device and Shut Off Valve	Flush 30	ND
17 Greek Way	Pot Sink without Filter	New Backflow Prevention Device and Shut Off Valve	Flush 30	ND
15 Greek Way	Pot Sink without Filter	New Backflow Prevention Device and Shut Off Valve	Flush 30	ND
CHEN	1 st Floor Pantry	New faucet, supply tubes, and valves	Grab	ND
Cypress	3 rd Floor Pantry (room 323)	New faucet and supply tubes	Grab	6
Library	2 nd Floor Pantry (room 2033)	New faucet, supply tubes, and valves	Grab	3

Drinking Water Sampling Locations and Results**Date Sampled: Friday May 6, 2016****Results Returned: Friday May 13, 2016**

Building	Location	Action	Sample Type	Results PPB
Fleisher Athletic	Basement Drinking Fountain	Installed Filter	Grab	ND
Fleisher Athletic	1st Floor Drinking Fountain	Installed Filter	Grab	ND
Fleisher Athletic	2nd Floor Drinking Fountain	Installed Filter	Grab	ND
Fleisher Athletic	Gym Hydration Station (Stair 5, Level 1)	Installed Filter	Grab	ND
Fleisher Athletic	3 rd Floor Hydration Station	Installed Filter	Grab	ND
Weston Hall	3 rd Floor Pantry Sink	New faucet and supply lines	Grab	3
Weston Hall	3 rd Floor Drinking Fountain	New internal components	Grab	13
Cypress Hall	4 th Floor Drinking Fountain (at Elevator)	N/A	Grab	ND
Cypress Hall	5 th Floor Drinking Fountain (at Elevator)	N/A	Grab	ND
Cypress Hall	6 th Floor Drinking Fountain (at Elevator)	N/A	Grab	1
Cypress Hall	7 th Floor Drinking Fountain (at Elevator)	N/A	Grab	ND
Cypress Hall	8 th Floor Drinking Fountain (at Elevator)	N/A	Grab	ND

Drinking Water Sampling Locations and Results**Date Sampled: Thursday April 28, 2016****Results Received: Thursday May 5, 2016**

Building	Location	Action	Sample Type	Results PPB
9 Greek Way	Kitchen Sink with New Filter	N/A	Grab	ND
9 Greek Way	Pot Sink Without Filter	New Back Flow Prevention Device and Main Shut Off Valve Installed	Grab	2
9 Greek Way	Newly Installed Back Flow Prevention Device (downstream sampling port)	N/A	Grab	8
EDC II	Main Sink with Newly Replaced Faucet	N/A	Grab	3
EDC II	Drinking Water Station with Upgraded Filter	N/A	Grab	ND

Drinking Water Sampling Locations and Results**Date Sampled: Thursday April 21, 2016****Results Received: April 28, 2016**

Building	Location	Action	Sample Type	Results PPB
EDC-2	Day Care Water Filter	N/A	Grab	ND
EDC-2	2 nd Floor Fountain by Suite 213	N/A	Grab	ND
Fenster	3 rd Floor Pantry Sink (room 396)	N/A	Grab	ND
Fenster	5 th Floor Pantry Sink (room 588)	N/A	Grab	ND
Library	2 nd Floor Pantry Sink (newly replaced)	Replace faucet and retest	Grab	74
Library	Faucet, valves, and supply tubes were subsequently replaced and re-sampled on 5/11 and returned acceptable results			
Cypress	3 rd Floor Drinking Fountain (near elevator)	N/A	Grab	ND
Cypress	2 nd Floor Drinking Fountain (near elevator)	N/A	Grab	ND
Cypress	3 rd Floor Pantry Sink (newly replaced)	Replace supply tubes and control valves and retest	Grab	637
Cypress	Faucet, valves, and supply tubes were subsequently replaced and re-sampled on 5/11 and returned acceptable results			
9 Greek Way	Sample Collected Directly From Back Flow Prevention Device (downstream sample port)	Replace Back Flow Prevention Device and Shut off Valve and Retest	Grab	1250

Drinking Water Sampling Locations and Results
Date Sampled: Thursday April 21, 2016
Results Returned April 28, 2016

Building	Location	Sample Type	Results (ppb)
Campus Center Kitchen	Double Sink A	Grab	ND
Campus Center Kitchen	Double Sink B	Grab	ND
Campus Center Kitchen	Pot Filler A	Grab	ND
Campus Center Kitchen	Pot Filler B	Grab	ND
Campus Center Kitchen	Pot Filler C	Grab	ND
Campus Center Kitchen	Steam Kettle	Grab	ND
Campus Center Kitchen	Pot Sink A	Grab	ND
Campus Center Kitchen	Pot Sink B	Grab	1
Campus Center Kitchen	Pot Sink C	Grab	ND
Campus Center Kitchen	Hand Sink 1	Grab	ND
Campus Center Kitchen	Utility Sink 1	Grab	ND
Campus Center Kitchen	Utility Sink 2	Grab	ND
Campus Center Kitchen	Hand Sink 2	Grab	2
Campus Center Kitchen	Utility Sink 3	Grab	ND
Campus Center Kitchen	Hand Sink 3	Grab	ND
Campus Center Food Service Area	Carving Hand Sink	Grab	ND
Campus Center Food Service Area	Entrée-Fajita Hand Sink	Grab	ND
Campus Center Food Service Area	Pizza Area – Pepsi Machine Water	Grab	ND
Campus Center Food Service Area	Pizza Area Utility Sink	Grab	ND
Campus Center Atrium	Pepsi Machine 1	Grab	ND
Campus Center Atrium	Pepsi Machine 2	Grab	ND
Campus Center Atrium	Gator Aide Machine	Grab	ND

Drinking Water Sampling Locations and Results
Date Sampled: Thursday April 20, 2016
Results Returned Thursday April 27, 2016

Building	Location	Action	Sample Type	Results PPB
Library	Lobby drinking fountain (lower fountain)	N/A	Grab	ND
Library	Lobby drinking fountain (upper fountain)	N/A	Grab	ND
Library	2 nd floor drinking fountain, outside restrooms	N/A	Grab	ND
Campus Center	2 nd floor lounge drinking fountain (lower fountain)	N/A	Grab	ND
Campus Center	2 nd floor lounge drinking fountain (upper fountain)	N/A	Grab	ND
Campus Center	3 rd floor staff dining area drinking fountain (lower fountain)	N/A	Grab	ND
Campus Center	3 rd floor staff dining area drinking fountain (upper fountain)	N/A	Grab	ND
Fenster	1 st floor drinking fountain (lower Fountain)	N/A	Grab	ND
Fenster	1 st floor drinking fountain (upper Fountain)	N/A	Grab	ND
Fenster	3 rd floor drinking fountain (lower Fountain)	N/A	Grab	ND
Fenster	3 rd floor drinking fountain (upper Fountain)	N/A	Grab	ND
York Center	1 st floor drinking fountain across from room 107	N/A	Grab	ND
York Center	1 st floor drinking fountain across from room 113	N/A	Grab	ND
York Center	2 nd floor drinking fountain across from room 209	N/A	Grab	ND
York Center	2 nd floor drinking fountain across from room 215	N/A	Grab	ND
York Center	3 rd floor drinking fountain across from room 307	N/A	Grab	ND
York Center	3 rd floor drinking fountain across from room 317	N/A	Grab	ND
CHEN Building	1 st floor pantry sink (post faucet replacement)	Replace supply tubes and control valves and retest	Grab	86
CHEN Building	Faucet, valves, and supply tubes were subsequently replaced and re-sampled on 5/11 and returned acceptable results			

Drinking Water Sampling Locations and Results

Date Sampled: Thursday April 7, 2016

Results Returned Thursday April 14, 2016

Building	Initial Sample Location	Certified Lab Initial Results (ug/L) (collected 4/7/2016)	Remedial Action Week of 4/18 to 4/22	Certified Lab Follow Up Sample Results PPB
Campus Center	1 st floor hand wash sink	1250	Sink removed from service	N/A
Central Avenue	2 nd floor kitchen sink	662	Faucets replaced	ND
Greek Residence 2	main level kitchen sink	550	Filtration installed	ND
York Center	2 nd floor men's room sink	542	Pending	Pending
Greek Residence 3	main level kitchen sink	379	Filtration installed	ND
Chen Building	1 st floor pantry sink	379	Faucets replaced	ND
Greek Residence 1	Main level kitchen sink	378	Filtration installed	ND
Fenster Hall	4 th floor men's room sink	79	Pending	Pending
EDC 2	main level kitchen sink	47	Filtration installed	ND
Greek Residence 5	main level kitchen sink	58	Filtration installed	N/A

Drinking Water Sampling Locations and Results

Date Sampled: Tuesday March 23, 2016 and

Results Returned Thursday April 7, 2016

(Initial and Follow Up Testing)

Building	Initial Sample Locations - Certified Laboratory	Certified Lab Initial Results PPB	Certified Lab Follow Up Sample Results PPB	Initial Sample Locations - City of Newark Laboratory	City of Newark Lab Initial Sample Results PPB	Action
Colton Hall	2nd floor kitchen sink	77.4	ND	4 th floor water fountain	24	Repairs In Progress; Water Provided
Weston Hall	3rd floor kitchen sink	59.6	65	3 rd floor drinking fountain	118	Faucet Replaced; Fountain Re-Built; Water Provided; Fountain and Faucet Retested
Fleisher Athletic Ctr.	basement hall water fountain	33.2	112	1 st floor drinking fountain	N/A	Fountains Taken out of Service; Filters Installed; Water Provided; Fountains Retested
Cullimore Hall	2nd floor water fountain	27.3	71	6 th floor drinking fountain	22	Internal Components Replaced; Fountains Retested
Specht Hall	1st floor water fountain	23.8	587	1 st floor drinking fountain	153	Fountain Taken out of Service; Water Provided
Tiernan Hall	4th floor kitchen sink	18.6	20	1 st floor drinking fountain	18	Fountains Taken out of Service; Scheduled for Replacement; Water Provided
Cypress Hall	3rd floor kitchen sink	N/A	411	1 st floor kitchen sink	N/A	Faucet, Supply Tubes, Valves Replaced; Water Provided; Faucets Retested
Campbell Hall	4 th floor kitchen sink	12.6	2	5 th floor kitchen sink	655	Faucet, Supply Tubes, Valves Replaced; Water Provided; Faucets Retested
FMH	2 nd floor drinking fountain	7.1	N/A	2 nd floor drinking fountain	53	In Progress, Water Provided
Eberhardt	Basement pantry sink	1.1	N/A	1 st floor pantry sink	51	Replaced Valves; Faucet Retested